

# Leak Detection and Repair (LDAR) Annual Report Form<sup>1</sup>



Please submit via email to: [cdphe\\_reg7LDAR\\_annualreports@state.co.us](mailto:cdphe_reg7LDAR_annualreports@state.co.us)

## Section 1: General Information

Company Name:	DJ Resources LLC		
Inspection Year:	2017	# Facilities Inspected: <sup>2</sup>	4
Contact Person:	Ryan Becker	Title:	Environmental Consultant
Phone Number:	303-956-3159	E-mail Address:	<a href="mailto:ryan_becker@golder.com">ryan_becker@golder.com</a>

## Section 2: LDAR Inspections

Inspection Method	# Inspections <sup>3</sup>
AIMM at Natural Gas Compressor Stations:	NA
AIMM at Well Production Facilities:	4
AVO at Well Production Facilities:	48
<b>TOTAL</b>	<b>52</b>

## Section 3: Leaking Components Details

Component Type	# Leaks Identified <sup>4</sup>	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	0	0	0
Connectors:	1	1	0
Flanges:	0	0	0
Pump Seals:	0	0	0
Pressure Relief Devices:	0	0	0
<b>TOTAL</b>	<b>1</b>	<b>1</b>	<b>0</b>

## Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Dominic Bazile	Executive Vice President & COO
Signature:	Date:
	3/31/17

