

Leak Detection and Repair (LDAR) Annual Report Form¹



Please submit via email to: cdphe_reg7LDAR_annualreports@state.co.us

Section 1: General Information

Company Name:	Crestone Peak Resources Operating, LLC		
Inspection Year:	2016	# Facilities Inspected: ²	249
Contact Person:	Taryn Weiner	Title:	Air Quality Specialist
Phone Number:	303-774-3908	E-mail Address:	taryn.weiner@crestonepr.com

Section 2: LDAR Inspections

Inspection Method	# Inspections ³
AIMM at Natural Gas Compressor Stations:	
AIMM at Well Production Facilities:	
AVO at Well Production Facilities:	
TOTAL	1535

Section 3: Leaking Components Details

Component Type	# Leaks Identified ⁴	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	40		
Connectors:	195		
Flanges:	22		
Pump Seals:	0		
Pressure Relief Devices:	103		
TOTAL	360	360	0

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Jason Oates	Director, Environmental, Regulatory & Community Affairs
Signature:	Date:
	7/18/17