



Newmont Mining Corporation
Cripple Creek & Victor Gold Mining Company
100 N 3rd St
P.O. Box 191
Victor, CO 80860
www.newmont.com

January 4, 2018

SENT CERTIFIED RETURN RECEIPT REQUESTED
7015-3010-0000-7164-2399

Ms. Kelly Morgan
Colorado Department of Public Health and Environment
Water Quality Control Division
WQCD-P-B2
4300 Cherry Creek Drive South
Denver, CO 80246-1530

RE: Colorado Discharge Permit System No. CO-0024562
RE: Failure to Submit Discharge Monitoring Report Carlton Tunnel Portal Site, CO0024562
Discharge Monitoring Reports - Discharge Numbers 2YCX and 2YDX
Monitoring Period – July 1, 2017 through September 30, 2017

Dear Ms. Morgan:

Cripple Creek & Victor Gold Mining Company (CC&V) hereby submits Discharge Monitoring Reports ("DMRs")s for Discharge Numbers 2YCX, and 2YDX, as required under Colorado Discharge Permit System ("CDPS") No. CO-0024562. All parameters reported on the attached DMR's are within the limits established in the permit.

The failure to submit a complete DMR packet is the result of a clerical error wherein all necessary components of the DMR were not included within the original submission. To address this oversight and implement actions to remedy the cause, a new review process has been implemented to insure that all DMR's sent will be complete.

Thank you for your time as it pertains to this matter, and should you have any further questions or comments, please contact Ronald Parratt, Environmental Specialist, at (719) 689-4019.

Sincerely,

A handwritten signature in black ink, appearing to read "Meg Burt".

Meg Burt
Senior Environmental Manager
Cripple Creek & Victor Gold Mining Co