



Newmont Mining Corporation
Cripple Creek & Victor Gold Mining Company
100 N 3rd St
P.O. Box 191
Victor, CO 80860

www.newmont.com

May 15, 2018

SENT CERTIFIED RETURN RECEIPT REQUESTED
7017-2400-0000-4077-7909

Ms. Kelly Morgan
Colorado Department of Public Health and Environment
Water Quality Control Division
WQCD-P-B2
4300 Cherry Creek Drive South
Denver, CO 80246-1530

RE: Colorado Discharge Permit System No. CO-0024562
Discharge Monitoring Reports - Discharge Numbers 001A-D and 002A-D
Monitoring Period – April 1, 2018 through April 30, 2018

Discharge Monitoring Reports - Discharge Numbers 01AX-DX, 1YAX-1YDX, 02AX-02DX, and 2YAX-2YDX
Monitoring Period – January 1 through April 30, 2018

Dear Ms. Morgan:

Cripple Creek & Victor Gold Mining Company ("CC&V") has completed the appropriate sampling, testing, and data collection for the monthly (April 2018) Discharge Monitoring Reports ("DMRs")s for Discharge Numbers 001A-D, and 002A-D, as required under Colorado Discharge Permit System ("CDPS") No. CO-0024562. All parameters reported on the attached DMR's are within the limits established in the permit.

CC&V has completed the appropriate sampling, testing, and data collection for the second Quarter (January through April 2018) DMRs for Discharge Numbers 01AX-DX, 1YAX-DX, 02AX-DX, and 2YAX-DX, as required under CDPS No. CO-0024562. Completion of the reporting requirements as outlined in part I.4.a of the Permit are also included in this report. All parameters reported on the attached DMRs are within the limits established in the permit

Thank you for your time as it pertains to this matter, and should you have any further questions or comments, please contact Ronald Parratt, Environmental Specialist, at (719) 689-4019.

Sincerely,

A handwritten signature in black ink, appearing to read "Meg Burt".

Meg Burt
Senior Environmental Manager
Cripple Creek & Victor Gold Mining Co