



Newmont Mining Corporation
Cripple Creek & Victor Gold Mining Company
100 N 3rd St
P.O. Box 191
Victor, CO 80860

www.newmont.com

June 28, 2018

SENT CERTIFIED RETURN RECEIPT REQUESTED
7017-2400-0000-4077-8913

Ms. Kelly Morgan
Colorado Department of Public Health and Environment
Water Quality Control Division
WQCD-P-B2
4300 Cherry Creek Drive South
Denver, CO 80246-1530

RE: Re-submittal
Colorado Discharge Permit System No. CO-0024562
Discharge Monitoring Report - Discharge Numbers 002C
Monitoring Period – September 1, 2016, through September 30, 2016

Dear Ms. Morgan:

Cripple Creek & Victor Gold Mining Company ("CC&V") hereby re-submits the monthly (September 2016) Discharge Monitoring Reports ("DMRs") for Discharge Number 002C. This re-submission is due to an error in the original submission. The value for average flow in conduit was incorrectly calculated and reported in the original submission. The correct average flow value for outfall 002C is included in this DMR submission. All parameters reported in the attached DMRs are within the limits established in the permit.

Should you have any further questions or comments, please contact Ronald Parratt, Water Specialist, at (719) 689-4019.

Sincerely,

A handwritten signature in black ink, appearing to read "Meg Burt".

Meg Burt
Senior Environmental Manager
Cripple Creek & Victor Gold Mining Co