

Dominion Energy Services, Inc.
5000 Dominion Boulevard
Glen Allen, VA 23060
DominionEnergy.com



Submitted via Email

April 17, 2018

Colorado Department of Public Health and Environment
Air Pollution Control Division
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

RE: Leak Detection and Repair Annual Report

Dear Air Pollution Control Division:

Wexpro Company is submitting the enclosed Leak Detection and Repair (LDAR) Annual Report Form, as required under Regulation 7, Section XVII.F.9.

If you should have any questions regarding this submittal, please contact Dani Baldwin at Dani.Baldwin@dominionenergy.com or (801) 324-3062.

Sincerely,

A handwritten signature in blue ink, appearing to read "R. Gangle".

Richard B. Gangle
Director, Environmental Services

Enclosed: Leak Detection and Repair Annual Report

Leak Detection and Repair (LDAR) Annual Report Form¹



Please submit via email to: cdphe_reg7LDAR_annualreports@state.co.us

Section 1: General Information

| | | | |
|------------------|----------------|--------------------------------------|--|
| Company Name: | Wexpro Company | | |
| Inspection Year: | 2017 | # Facilities Inspected: ² | 162 |
| Contact Person: | Dani Baldwin | Title: | Environmental Specialist III |
| Phone Number: | 801-324-3062 | E-mail Address: | Dani.Baldwin@dominionenergy.com |

Section 2: LDAR Inspections

| Inspection Method | # Inspections ³ |
|--|----------------------------|
| AIMM at Natural Gas Compressor Stations: | 0 |
| AIMM at Well Production Facilities: | 256 |
| AVO at Well Production Facilities: | 1,944 |
| TOTAL | 2,200 |

Section 3: Leaking Components Details

| Component Type | # Leaks Identified ⁴ | # Leaks Repaired | # Leaks on Delay of Repair List as of Dec 31 |
|--------------------------|---------------------------------|------------------|--|
| Valves: | 61 | 61 | 0 |
| Connectors: | 135 | 135 | 0 |
| Flanges: | 0 | 0 | 0 |
| Pump Seals: | 0 | 0 | 0 |
| Pressure Relief Devices: | 38 | 38 | 0 |
| TOTAL | 234 | 234 | 0 |

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

| | |
|--|---|
| Printed/Typed Name - Responsible Official: | Title: |
| Brady Rasmussen | Wexpro Vice President & General Manager |
| Signature: | Date: |
| | 4/16/18 |

