



STATE OF
COLORADO

Reg7LDAR_AnnualReports - CDPHE, CDPHE <cdphe_reg7ldar_annualreports@state.co.us>

Wiepking-Fullerton - 2014 LDAR Annual Report

1 message

Aimee Cole <acole@ltenv.com>

Fri, May 29, 2015 at 12:23 PM

To: "cdphe_reg7ldar_annualreports@state.co.us" <cdphe_reg7ldar_annualreports@state.co.us>

Please see the attached 2014 LDAR Annual Report submitted on behalf of Wiepking-Fullerton Energy.

Let me know if you have any questions or require any additional information.

Thank you,

Aimee Cole
Project Geologist



COMPLIANCE / ENGINEERING / REMEDIATION

LT Environmental, Inc.

(720) 384-7365 cell

www.ltenv.com

acole@ltenv.com

Take our [LTE Client Satisfaction Survey](#)



May 29, 2015

Sent Via Email

**RE: 2014 LDAR Annual Report
Wiepking-Fullerton Energy, LLC**

To Whom It May Concern:

Please find attached the 2014 LDAR Annual Report, as required under Regulation No. 7, Section XVII.F, submitted on behalf of Wiepking-Fullerton Energy, LLC for sites which are located in Lincoln County, Colorado.

If you have any questions or need additional information, please do not hesitate to contact me at (303) 962-5555 or by email at cpowell@ltenv.com.

Sincerely,

LT ENVIRONMENTAL, INC.

A handwritten signature in black ink that reads 'Chad Powell'. The signature is written in a cursive, flowing style.

Chad Powell, Air Quality Manager

cc: Linda Boone – Wiepking-Fullerton Energy, LLC



Leak Detection and Repair (LDAR) Annual Report Form

(Version December 18, 2014)
Regulation 7, Section XVII.F.9

Section 1: General Information

Company Name:	Wiepking-Fullerton Energy, LLC		
Inspection Year:	2014	# Facilities Inspected: ¹	1
Contact Person:	Linda Boone	Title:	Agent
Phone Number:	(720) 941-0791	E-mail Address:	LDBoonePar@aol.com

¹ Identify the list of facilities inspected in the Addendum Table 1 in Section 5

Section 2: LDAR Inspections

Inspection Method	# Inspections
AIMM at Natural Gas Compressor Stations:	N/A
AIMM at Well Production Facilities:	1
AVO at Well Production Facilities:	N/A
TOTAL	1

Section 3: Leaking Components Details


Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:			
Connectors:	1	1	N/A
Flanges:			
Pump Seals:			
Pressure Relief Devices:			
TOTAL	1	1	0

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7-122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Jeff Wiepking	Manager
Signature:	Date:
	5/28/15

Join us on:



This message and any attached files are privileged, confidential, and intended solely for the use of the addressee. If you have received this by mistake, please let us know by reply e-mail and delete it from your system; you may not copy, disclose, disseminate, use or rely upon its content for any use. E-mail transmissions cannot be guaranteed to be secure, error-free, or free of viruses. The sender and LTE therefore do not accept liability for any of these described issues. The comments and opinions expressed herein are those of the author and not necessarily of LTE. Thank you.



Please consider the environment before printing this e-mail.

2 attachments



image005.png
2K



Wiepking-Fullerton LDAR Annual Report - 2014.pdf
160K