



Newmont Mining Corporation
Cripple Creek & Victor Gold Mining Co.
100 North 3rd Street P O Box 191
T 719-689-2977
F 719-689-3254
www.newmont.com

SENT CERTIFIED, RETURN RECEIPT REQUESTED
7015-1660-0000-.0779-8072

July 20, 2016

Ms. Kelly Morgan
Colorado Department of Public Health and Environment
Water Quality Control Division
WQCD-P-B2
4300 Cherry Creek Drive South
Denver, CO 80246-1530

RE: Colorado Discharge Permit System No. CO-0024562
Discharge Monitoring Reports - Discharge Numbers 001A-D and 002A-D
Monitoring Period – June 1, 2016 through June 30, 2016

Discharge Monitoring Reports - Discharge Numbers 01AX-DX, 1YAX-1YDX, 02AX-02DX, and 2YAX-2YDX Monitoring
Period – May 1, 2016 through June 30, 2016

Dear Ms. Morgan:

Cripple Creek & Victor Gold Mining Company ("CC&V") has completed the appropriate sampling, testing, and data collection for the monthly (June 2016) Discharge Monitoring Reports ("DMRs")s for Discharge Numbers 001A-D, and 002A-D, as required under Colorado Discharge Permit System ("CDPS") No. CO-0024562. All parameters reported on the attached DMR's are within the limits established in the permit.

CC&V has completed the appropriate sampling, testing, and data collection for the second Quarter (May and June 2016) DMRs for Discharge Numbers 01AX-DX, 1YAX-DX, 02AX-DX, and 2YAX-DX, as required under CDPS No. CO-0024562. Completion of the reporting requirements as outlined in part I.4.a of the Permit are also included in this report. All parameters reported on the attached DMRs are within the limits established in the permit.

Thank you for your time as it pertains to this matter, and should you have any further questions or comments, please contact Bleys- Andromeda Focht, Environmental Technician III, at (719) 689-4060.

Sincerely,

A handwritten signature in black ink, appearing to read "Meg Burt".

Meg Burt
Manager, Environmental Resources