



May 04, 2016

Mr. Mark McMillan  
Colorado Department of Public Health & Environment  
Air Pollution Control Division  
4300 Cherry Creek Drive South  
Denver, Colorado 80246-1530

**RE: Regulation 7 LDAR 2015 Annual Report**

Dear Mr. McMillan,

WPX Energy Rocky Mountain, LLC (WPX Energy), is submitting an annual report for 2015 LDAR Inspections as required per Regulation Number 7, Section XVII.F.9.

If you require additional information or have any questions, please contact me at 970-263-2792, or by email at [Brandon.Danforth@wpxenergy.com](mailto:Brandon.Danforth@wpxenergy.com).

Sincerely,

*WPX Energy Rocky Mountain, LLC*

A handwritten signature in blue ink, appearing to read "BDanforth", written over a light blue horizontal line.

Brandon Danforth  
Environmental Supervisor

Enclosures

### Regulation 7 Leak Detection and Repair (LDAR) Annual Report

**General Information**

Company Name:	WPX Energy Rocky Mountain, LLC	Inspection Year:	2015
---------------	--------------------------------	------------------	------

**LDAR Inspection Counts**

# Facilities Inspected	1019	# Inspections	3558
------------------------	------	---------------	------

**Component Leaks and Repairs**

Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	2	2	0
Connectors:	5	5	0
Flanges:	1	1	0
Pump Seals:	0	0	0
Pressure Relief Devices:	1	1	0

**Responsible Official Certification**

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.	
Printed/Typed Name - Responsible Official:	Title:
JoDell Mizoue	Environmental Manager
Signature:	Date: 5/4/16